

ELECTRICAL SAFETY RECALL



Turbo Dust Interceptor

Identifiers:

This recall applies to the Turbo Dust Interceptor, with model number 31300479 shown on the base of the box. This product was sold since the beginning of 2008 at all Godfreys stores nationally. These units were only compatible with the following Wertheim vacuum cleaner models; 6035, 6030, x5000, 3030T, 4430, 4410 and 4412.

These Turbo Dust Interceptors may contain unstable internal pins which if dislodged, could pose a potential risk of electrical shock, burns, or in rare circumstances electrocution.

Customers are advised to immediately cease use of the product and disconnect it from the hose of the vacuum cleaner. You must not operate your machine with this unit attached. Once removed, you can continue using your vacuum as normal without any further risk.

PLEASE RETURN THIS PRODUCT TO YOUR NEAREST GODFREYS STORE FOR A FULL REFUND.

For further information, please call our toll-free Customer Service Number on:

0800 282 288 Mon-Fri between 9am -5pm NZST.
International Cleaning Solutions Holding Pty Ltd (Godfreys)
17-21 Cavendish Drive Manukau, Auckland NZ

www.godfreys.co.nz